Revise as follows:

TABLE R408.2.3

Service water -heating efficiencies

Portions of table not shown remain unchanged.