This	is	the	annual	energy	use	data	for	Energy	Star	Certified

Finally, other IECC

-R sections employ "all" when needed to m ake the intent clear. The same is

proposed here

.

Prevent Future Installation of Less

-Efficient Clothes Washers at Plumbed Locations

In some buil dings, some (typically the larger) dwelling units are plumbed for washers and

common

area laundry facilities are provided. Footnote "a" to Table R408.2

provides that washers must be

i nstalled in both the plumbed dwelling units and the common area(s). But that shou ld be stated

explicitly in this section. The idea is to avoid future (e.g., post

-COO) installation of less efficient

ap pliances in plumbed dwelling units.

The loopholes described above are closed by the proposed changes.

Cl othes Washers Located Outside Dwelling Units

The phrase "Where dwelling units are not provided with laundry facilities" in Table R408.2.6 is

commonly interpreted as 'where dwellin g units are no t

provided with a common area laundry room.'

That is not what the proponents intended. The proposed change conveys the proponents' intent.

Reference: